

Shoshone 65-38

Plug and Abandonment Procedure

Well Information

Field: Circle Ridge

County: Fremont County, Wyoming

Legal: 0' FNL & 0' FEL Section 36 T7N R3W

Lat/Long: 43.5354, -109.05777

API#: 4901306845

Ground level elevation	7,229'	KB Elevation:	7,238'		
TD:	4,030'	PBTD:	1,192'		
Surface Casing:	13-3/8" 48.0 #/ft @ 154'	13-3/8" 48.0 #/ft @ 154'			
Surface Casing Cement:	100 sx				
Surface Casing TOC:	Surface	Source:	Drilling Report	-	
Production Casing;	5-1/2" 14.0, 15.5, & 17.0 #/	5-1/2" 14.0, 15.5, & 17.0 #/ft @ 1,217'			
Production Casing Cement	100 sx				
Production Casing TOC	715' Surface (Remedial Job)	Source:	Calculation Workover Rpt (05/2015)		
Production Tubing	2-7/8" 6.5 #/ft tubing and p	2-7/8" 6.5 #/ft tubing and packer			
Open perforations	Embar: 882' – 1,152'	Embar: 882' – 1,152'			
Well Status	Shut In Injector				

Note: All cement pumped for this procedure will be 15.8 ppg Class G neat cement with a yield of 1.16 cu. Ft/sk and .3% by weight dispersant added.

Plugging Procedure

- 1. MIRU, pull all tubing, packers, rods, and pumps out of hole.
- 2. Run Bit and Scraper to PBTD.
- 3. Set CICR 50' above the top perforation @ 832'.
- 4. Pump 1.5x wellbore volume (60 sx) of cement below CICR.
- 5. Sting out of CICR, pump 25 sx on top of retainer.
- 6. WOC 24 hours.
- 7. Pressure test production casing to a minimum of 500 psi for 10 minutes.
- 8. RIH with 2 3/8" 4.9#/ft tubing to 200' below surface.
- 9. Pump balance plug from 200' to surface inside production casing.
- 10. WOC 24 hours. If cement level has fallen top off production casing with cement back to surface utilizing 1" poly hose.
- 11. Cut casing 3' below grade and weld on dry hole plate w/ legal ID. Remove rig anchors.

Wellbore Diagram

